

# “Recovery measures in Serizawa District”

## Aiming for reconstruction from the damage of the Kanto and Tohoku heavy rain disaster



The disaster situation confirmed from a helicopter (From Takimukaisawa to Nakatsubo Shimosawa in Serizawa District)

Sabo dam construction after the damage

### ■ Protecting a region where people live from damage

In order to prevent recurrence of disasters in Serizawa District, all of the sabo work was completed by March 2017 for Shimo-Serizawa, Shimotsubo Kamisawa, Udonsawa, Takimukaisawa, Nakatsubo Shimosawa, and Nakatsubo Kamisawa. Work is continuing on the Serizawa River.

