

# “Jyoryu Sabo Dam No. 10 ” Effective for trapping debris floods

## ■ Prevention of damage from a second disaster

One of the sabo dams constructed with the aim of controlling debris floods from the Inari River, located upstream of the Sabo Dam No. 10, a Registered Tangible Cultural Property and a Civil Engineering Heritage Site. It trapped debris floods and driftwood during Typhoon No. 12 in August-September 2011 and Typhoon No. 18 in September 2015, and protected the downstream area against damage.



Before the debris flood occurred  
Debris deposit line caused by Typhoon No. 18 in 2015



After the debris flood occurred

平成20年6月27日撮影